

LKR - LANCASTER COUNTY-MC WHIRTER FIELD

LANCASTER - 38

CHARLOTTE SECTIONAL

Latitude: 34° 43' 22.4558" N

12/28/2023

Longitude: 80° 51' 16.5243" W



Elevation - 486' MSL

Mag Var - 08° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
06/24	6004'	101'	CONC	06/24	06/24	MED		Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
06/24	44.0	60.0	118.0		LKR	NDB	400	at fld
					CLT	VORTAC	115.00	r175° 28.4 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
122.725	122.725			120.05	CLT	120.825	(803) 286-6444

Manager Paul Moses / Director

Storage HGR,TIE

Repairs N

GPS 286 Aviation Blvd

Landing Fee Y

Oxygen N

Address Lancaster, SC 29720

Lighting Sched SEE RMK

Fuel Type 100LL, JET A

Phone (803) 285-1513

Att Schedule M-F 0700-1500

Fax (877) 241-7297

Remarks ACTVT MIRL - CTAF
 TERMINAL ACCESS KEYPAD FIRST FIVE
 DIGITS UniCom PLUS ASTERISK KEY.
 SELF SERVICE 100LL and JET A

Email pmoses@lancasteresc.net

FBO Phone/Fax

Lancaster County Airport
 (803) 285-1513