

LQK - PICKENS COUNTY
 ATLANTA SECTIONAL
 12/28/2023

PICKENS - 55

Latitude: 34° 48' 35.9000" N
Longitude: 82° 42' 10.4000" W



Elevation - 1013' MSL

Mag Var - 06° W

Runway						Edge	Approach	Traffic
ID	Length	Width	Surface	VGSI	REILS	Lights	Lights	Pattern
05/23	5002'	100'	ASPH	05/23		MED		Standard

Runway Pavement Strength					Navigation			
Runway	SW	DW	DTW	DDTW	IDENT	Type	FREQ	Direct/Dist
05/23	75.0	101.0			ELW	VORTAC	108.60	r10° 23.8 NM to fld

Communications				ATC		AWOS/ASOS	
UniCom	CTAF	GCO	RCO	FREQ	FAA ID	FREQ	Phone
122.800	122.800			118.8	GSP	120.000	(864) 843-5801

Manager Carlos Salinas	Storage HGR,TIE	Repairs Y
GPS 240 Airport Rd	Landing Fee N	Oxygen N
Address Liberty, SC 29657	Lighting Sched SEE RMK	Fuel Type 100LL, JET A
Phone (864) 843-5803		
Fax	Att Schedule Daily 0800-1700	
Email csalinas@co.pickens.sc.us	Remarks Noise Abatement Procedures In Effect ACTVT MIRL - CTAF. After hours access use UniCom freq SELF SERVICE 100LL	
FBO Phone/Fax		
Pickens County Aviation (864) 843-5803		